

Revised Manifest Summary Report

POPE AND TALBOT
POPE AND TALBOT

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
09/29/1989		88440435		0	LBS		CMP		
10/02/1989		88440433		0	LBS		CMP		
10/03/1989		88440432		0	LBS		CMP		
10/05/1989		88440431		0	LBS		CMP		

Total Records: 4

Default Volume: 0

Total Waste Volume: 0

generator_name	POPE AND TALBOT	2566
lc_name:	POPE AND TALBOT	
lc_calc_volume:	74.226 tons	
manifest_number	manifest_quantity_ton	
88440431	8.757 tons	
88440432	20.85 tons	
88440433	25.02 tons	
88440435	19.599 tons	

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. OR D 0019 GH 2870 CICK01	Monitor No. 	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address POPG AND TALBOT 48513 HIGHWAY 126 OAKRIDGE, OREGON 97463		A. State Manifest Document Number 88440435			
4. Generator's Phone 503 752 2251		B. State Generator's ID			
5. Transporter 1 Company Name NHL BULK SERVICES, INC.		C. State Transporter's ID 58CP-101			
6. Transporter 1 Company Name 		D. Transporter's Phone 415 8870537			
7. Transporter 2 Company Name 		E. State Transporter's ID			
8. Recipient Facility Name and Site Address OMEGA RECOVERY EXP'G 2504 EAST WHITTIER BLVD. WHITTIER, CA. 90602		F. Transporter's Phone			
9. US EPA ID Number CAD043245091		G. State Facility's ID			
10. US EPA ID Number 213698091		H. Facility's Phone			
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number) HAZARDOUS WASTE LIQUID, N.O.S., ORM-E, NA 9189		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L Waste No.
		6	003 TT04790 G	State	231
				EPA/Other	
12. Containers Type				State	
				EPA/Other	
13. Total Quantity				State	
				EPA/Other	
14. Unit Wt/Vol				State	
				EPA/Other	
15. Special Handling Instructions and Additional Information ALWAYS WEAR PERSONAL PROTECTIVE EQUIPMENT WHEN HANDLING HAZARDOUS WASTES.		J. Additional Descriptions for Materials Listed Above SPILLED RENTACHLOROPHENOL AND RAIN WATER = .3% PENTACHLOROPHENOL			
		K. Handling Codes for Waste(s) Listed Above a. b.			
		c. d.			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations.		Signature Roger V. Hayes Month Day Year 10/29/89			
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name RONALD ANSTED		Signature Ronald Ansted Month Day Year 09/29/89			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name 		Signature Month Day Year 			
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19 Printed/Typed Name FRANK FORD		Signature Frank Ford Month Day Year 11/02/89			

Do Not Write Below This Line

Within 10 days TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. GRD00904287000001	Manifest Document No.	2. Page 1 of /	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address POPG AND TALBOT 48513 HIGHWAY 58 OAKRIDGE, OREGON 97463		A. State Manifest Document Number 88440435			
4. Generator's Phone # 503 752 2251		B. State Generator's ID			
5. Transporter 1 Company Name NU BULK SERVICES, INC.		C. State Transporter's ID 59C9-101			
6. Transporter 2 Company Name		D. Transporter's Phone 416 8870537			
7. Transporter Facility Name and City Address OMEGA RECOVERY EXP'G. 12504 EAST WHITTIER BLVD. WHITTIER, CA. 90602		E. State Transporter's ID			
8. Transporter Facility Phone (CAD) 042245001		F. Transporter's Phone			
9. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HAZARDOUS WASTE LIQUID, N.O.S., ORM-E, NA 9189		G. State Facility's ID			
10. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) SPILLED PENTACHLOROPHENOL AND RAIN WATER = .3% PENTACHLOROPHENOL =		H. Facility's Phone 213 6980991			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) HAZARDOUS WASTE LIQUID, N.O.S., ORM-E, NA 9189		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L Waste No.
		003	T.T.04790G		231
					State
					EPA/Other
					State
					EPA/Other
					State
					EPA/Other
15. Special Handling Instructions and Additional Information ALWAYS WEAR PERSONAL PROTECTIVE EQUIPMENT WHEN HANDLING HAZARDOUS WASTES.		K. Handling Codes for Wastes Listed Above			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.		a. b.			
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.		c. d.			
Printed/Typed Name ROGER V. HAYES		Signature <i>Roger V. Hayes</i>		Month Day Year 1092989	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name KONRAD ANSTED		Signature <i>Konrad Ansted</i>		Month Day Year 092989	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name FRANK FORD		Signature <i>Frank Ford</i>		Month Day Year 1102489	

0022 A (1/88)

5700-22

Previous editions are obsolete.

Do Not Write Below This Line

Within 30 DAYS
To: P.O. Box 3000, Sacramento, CA 95812